



FIG. 1



\square : 650°C , \blacktriangle : 750°C , \blacktriangledown : 850°C , \blacksquare : 950°C , \bullet : graphite

FIG. 2



●: pressurization #1, ○: depressurization #1, ■: pressurization #2, □: depressurization #2.

FIG. 3






FIG. 4

Fig. 5a



Solid line: 20/40 mesh. Dashed line: powder.
Each curve shows depressurization #2.

Fig. 5b



Left side: 20/40 mesh. Right side: powder.
●: pressurization #1, ○: depressurization #1,
■: pressurization #2, □: depressurization #2.